


SCHOOL BUILDING SAFETY CERTIFICATE

This is to certify that, the building of Residential school at Bhuratali School located at Sabroom, South Tripura District is in good and stable condition. The undersigned have visited the school building on 11/11/2021 which is an RCC framed structure, G+1. The Building materials used are as per BIS norms and specifications which is constructed by RD Engineering wing during the year 2006-07. There is no doubt about its safety.


(Er U. Jamatia)
Superintending Engineer
RD 2nd Circle, Udaipur
Gomati District.